

BMW Group - AIR: 2018-10-01 / 08:29
Autorizovaný partner BMW: 42732/01
Model: 330xi
Identifikační číslo vozidla: A029599
Vývojové označení: E90
Kód typu: VD41
Typ vedení: VD41
Číslo objednávky: -

Instrukce oprav

Removing and installing/replacing cover on front door handle (passenger side) (3 PJ)

51 41 017 | REP-REP-RAE9051-5141017 - V.3

51 41 017 Removing and installing/replacing cover on front door handle (passenger side)




Special tools required:

- 00 9 317



Necessary preliminary tasks:

- Remove decorative strip from front door (passenger side)



Lever out cover (1) with special tool 00 9 317.

Installation:

Catches (1) of cover (2) must not be damaged.

